Abstract estimate for restoring Kunkumanahalli minor tank Reg. No. 5 of Tumkur Taluk :—

No.	Item of work	Quantity	
	Bund at R. L. 54·00 top width 4½ feet :—		
1	Earthwork to bund with watering and tamping, etc. ...	C. yd.	7,775
2	Turfing to earth slopes	S. yd.	8,208
3	Fixing new grade stones, figuring and painting ...	Each	31
4	Do B. M. stones do	Do	2
5	Do Reg. No. stones do	Do	1
6	Removing jungle and ant-hills on bund	...	L. S.
7	Constructing a burnt stone slab drain between C. S. 1 and C. S. 2 across feeder hall.	...	Do.
	Sluice :—		
8	Constructing a stone ware pipe sluice at R. L. 47·00 ...	Do	...
	Weir 100 feet long at R. L. 50·00 :—		
9	Earthwork, excavating foundation for body wall, etc., is chargeable to bund.	...	Do.
10	Burnt brick in surki mortar	C. ft.	357
11	Burnt stone slabs 4″ to 6″ thick	S. ft.	122
12	Surki plastering	Sq.	2·00
13	New rough stone work	C. yd.	38

ANANDA RAO SIRSI,
Deputy Commissioner.

OFFICE OF THE SUPERINTENDENT, GOVERNMENT PRINTING IN MYSORE, BANGALORE.

Notice dated 10th December 1920.

Notice is hereby given that unserviceable articles of the Government Branch Press, Mysore, as specified below, will be sold by public auction on Saturday the 29th January 1921, commencing at 2 P.M., at the Branch Press premises. The highest bidder shall be the purchaser, who will pay the purchase money before the articles are removed, failing which, the same will be resold at the risk of the original purchaser, who shall make good the loss, if any, between the original amount and the sum realised by the second sale, but shall not participate in any profit by such resale:

List of unserviceable articles to be auctioned.

No.	Names of articles	Quantity
1	Very old and spoiled printing inks, including Black, Light-green, Red, Brown, etc., 22 tins.	lbs. 13½
2	Broken composing sticks	Nos. 2
3	Big-sized shooting sticks (Iron broken)	„ 2
4	Candle stands another sort (small size)	„ 2
5	Broken mallets	„ 5
6	Very small bell	„ 1
7	Very old-fashioned candle stands (Iron)	„ 5
8	Bodkin (Broken)	„ 3
9	Brush	„ 1
10	Electric Bulbs (spoiled)	„ 39
11	One dealwood box containing 19 empty tins of printing ink, etc.	One dealwood box of 19 empty tins.
12	Two dealwood boxes containing spoiled roller composition ...	Two dealwood boxes.
13	Ink Jars	Nos. 3
14	Pieces of Motor Belt	„ 3
15	Pipe Cork	„ 2

D. B. RAMACHANDRA MUDALIAR,
Superintendent, Government Printing.